Compliance plan for NZTA Waikato DUML 2024

Deriving submission information			
Non-compliance	Description		
Audit Ref: 2.1 With: Clause 11(1) of	Database is not confirmed as accurate with a 95% level of confidence resulting in an estimated over submission of 105,300 kWh per annum.		
Schedule 15.3	37 discrepancies identified in the 2023	een corrected,	
	76 of 87 discrepancies identified in the last audit have not been corrected,		not been corrected, and
	Two items of load with zero wattage recorded.		
	Potential impact: High		
	Actual impact: High		
From: 01-May-24	Audit history: Multiple times previously.		
To: 07-Aug-24	Controls: Weak		
	Breach risk rating: 9		
Audit risk rating	Rationale for audit risk rating		
High	The controls are recorded to be weak because they don't ensure the database is accurate and the issues recorded in previous audits have not been remedied.		
	The impact is assessed to be high due to the estimated kWh impact.		
Actions taken to resolve the issue		Completion date	Remedial action status
Genesis continues to notify and provide NZTA with the audit findings and discrepancies identified and has continued to strongly recommend these are investigated and updated in their system.		Continuous Improvement	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
1000522354PCD90 profile has been changed to GSL		02/09/2024	

Description and capacity of load			
Non-compliance	Description		
Audit Ref: 2.4	Two items of load with zero wattage recorded.		
With: Clause 11(2)(c)	Nine items of load with unknown light make.		
and (d) of Schedule	Potential impact: Medium		
	Actual impact: Low		
	Audit history: Once		
From: 01-May-24	Controls: Moderate		
To: 07-Aug-24	Breach risk rating: 2		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are recorded as moderate because they mitigate risk most of the time but there is room for improvement.		
	The impact on settlement and participants is minor; therefore, the audit risk rating is low.		
Actions taken to resolve the issue		Completion date	Remedial action status
Genesis continues to notify and provide NZTA with the audit findings and discrepancies identified and has continued to strongly recommend these are investigated and updated in their system.		Continuous Improvement	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
Genesis continues to notify and provide NZTA with the audit findings and discrepancies identified and has continued to strongly recommend these are investigated and updated in their system.		Continuous Improvement	

All load recorded in database			
Non-compliance	Description		
Audit Ref: 2.5	14 additional items of load identified by the field audit.		
With: Clause 11(2A) of	Potential impact: High		
Schedule 15.3	Actual impact: Low		
	Audit history: None		
From: 01-May-24	Controls: Weak		
To: 07-Aug-24	Breach risk rating: 3		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are recorded as weak because they are not sufficient to ensure the database is accurate The impact on settlement and participants is minor; therefore the audit risk rating is low.		
Actions taken to resolve the issue		Completion date	Remedial action status
Genesis continues to notify and provide NZTA with the audit findings and discrepancies identified and has continued to strongly recommend these are investigated and updated in their system.		Continuous Improvement	Identified
Preventative actions taken to ensure no further issues will occur		Completion date	
Genesis continues to notify and provide NZTA with the audit findings and discrepancies identified and has continued to strongly recommend these are investigated and updated in their system.		Continuous Improvement	

Database accuracy		
Non-compliance	Description	
Audit Ref: 3.1 With: Clause 15.2 and 15.37B(b) From: 01-May-24	Database is not confirmed as accurate with a 95% level of confidence resulting in an estimated under submission of 105,300 kWh per annum. 37 discrepancies identified in the 2023 audit have not been corrected, 76 of 87 discrepancies identified in the last audit have not been corrected, and Two items of load with zero wattage recorded. Nine items of load with unknown light make. Submission is based on a snapshot and does not consider changes during the month. Potential impact: High	
To: 07-Aug-24	Actual impact: High Audit history: Multiple times previously Controls: Weak Breach risk rating: 9	
Audit risk rating	Rationale for audit risk rating	
High	The controls are recorded to be weak because they don't ensure the database is accurate and the issues recorded in previous audits have not been remedied. The impact is assessed to be high due to the estimated kWh impact.	

Actions taken to resolve the issue	Completion date	Remedial action status
Genesis and the auditors have continued to recommend a full audit be carried out. NZTA have advised there is no funding for a full field audit to be carried out and due to NZTA going under a new maintenance model change with an expected live date of March 2026, this is very unlikely to take place before then.	Continuous Improvement	Identified
Genesis continues to notify and provide NZTA with the audit findings and discrepancies identified and has continued to strongly recommend these are investigated and updated in their system.		
Preventative actions taken to ensure no further issues will occur	Completion date	
	1	1
Genesis and the auditors have continued to recommend a full audit be carried out. NZTA have advised there is no funding for a full field audit to be carried out and due to NZTA going under a new maintenance model change with an expected live date of March 2026, this is very unlikely to take place before then.	Continuous Improvement	

Volume information accuracy		
Non-compliance	Description	
Audit Ref: 3.2 With: Clause 15.2 and 15.37B(c)	Database is not confirmed as accurate with a 95% level of confidence resulting in an estimated over submission of 105,300 kWh per annum. 37 discrepancies identified in the 2023 audit have not been corrected, 76 of 87 discrepancies identified in the last audit have not been corrected, and Two items of load with zero wattage recorded.	
From: 01-May-24 To: 07-Aug-24	Potential impact: High Actual impact: High Audit history: Multiple times previously. Controls: Weak	
Audit risk rating	Breach risk rating: 9 Rationale for audit risk rating	
High	The controls are recorded to be weak because they don't ensure the database is accurate and the issues recorded in previous audits have not been remedied. The impact is assessed to be high due to the estimated kWh impact.	

Actions taken to resolve the issue	Completion date	Remedial action status
Genesis and the auditors have continued to recommend a full audit be carried out. NZTA have advised there is no funding for a full field audit to be carried out and due to NZTA going under a new maintenance model change with an expected live date of March 2026, this is very unlikely to take place before then.	Continuous Improvement	Identified
Genesis continues to notify and provide NZTA with the audit findings and discrepancies identified and has continued to strongly recommend these are investigated and updated in their system.		
Preventative actions taken to ensure no further issues will occur	Completion date	
Genesis and the auditors have continued to recommend a full audit be carried out. NZTA have advised there is no funding for a full field audit to be carried out and due to NZTA going under a new maintenance model change with an expected live date of March 2026, this is very unlikely to take place before then.	Continuous Improvement	
Genesis continues to notify and provide NZTA with the audit findings and discrepancies identified and has continued to strongly recommend these are investigated and updated in		