Compliance plan for Parawera Community Lighting Manawa 2024

All load recorded in database			
Non-compliance	Description		
Audit Ref: 2.5 With: Clause 11(2A) of	One extra light was found in the field. Potential impact: Low		
Schedule 15.3	Actual impact: Low		
From: 01-May-21 To: 03-Apr-24	Audit history: None Controls: Weak		
	Breach risk rating: 3 Pationals for audit rick rating		
Audit risk rating	Rationale for audit risk rating		
Low	The controls are recorded as weak as the database contacts are not current and no updates have been received. The impact on settlement and participants is minor; therefore, the audit risk rating is low.		
Actions taken to resolve the issue		Completion date	Remedial action status
Manawa has reached out to The Kingfisher RA chair to confirm that laser electrical is still the correct contractor to speak with regarding the discrepancies, so that the database can be updated on our end.		01/10/2024	Investigating
Once corrections are identified this will be applied to SLIM, backdated where applicable, and reconciled.			
Preventative actions taken to ensure no further issues will occur		Completion date	
Along with clarifying how the process is managed by the customer, a simple process change on our end will be to schedule regular automated reminders in our compliance system to alert our operations team inbox to contact Kingfisher throughout the year. This will reduce Key person risk and increase frequency of contact with the customer.		01/08/2024	